

MiLAN Technology

Release Notes



24 Port Switch plus 1 Module
MIL-SM2401M
Firmware Version 2.00
Kernel Version 2.10

Customer Release Notes

Fixes and Enhancements in this Version:

- 1.) System Kernel: Update kernel version to v2.10
- 2.) Spanning Tree was displaying the same MAC address for every port. This issue was resolved.

Known Limitations:

Software Limitation:

- 1.) If a flood of IGMP Query's or Reports are sent to the switch this causes the management to become unavailable for a period of time. This is due to the fact of the CPU processing all IGMP traffic before management traffic. Note: This only happens IGMP is enabled. This was test by a packet generator in a test environment and would not see this in real world scenario.