



---

## **S3290 Release Notes**

**Date: December 10, 2014**

**Version: 2.0.4**

---

### **Overview**

This release note covers known issues for the S3290 Carrier Ethernet NID.

### **Requirements:**

Firmware version 2.0.4 and these release notes apply to the following products:

- S3290-24
- S3290-42

### **Known Feature Limitations:**

The following is a list of currently known issues for the S3290.

- RFC2544 feature works with the S3290 as a generator. There is no reflector capability in this release.
- At the time of this release, some features like RFC2544 can only be configured via CLI or Web interface and are not manageable via SNMP.
- CLI commands for https, port description, port DMI configuration are not available at this time.

### **Related Documentation:**

Please visit the specific product web page for detailed documentation

- S3290 Install Guide (33594)
- Web User Guide (33595)
- CLI Reference Guide (33596)

### **MIBs:**

- tn-mibs-v2.0.4.zip