



---

## **IONPS-A-R1 Release Notes**

**Date: September 18, 2017**

**Version: 1.2.6**

---

### **Overview**

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the IONPS-A-R1 power supply modules used in the ION 19-slot chassis.

### **Requirements:**

Firmware version 1.2.6 and these release notes apply to the following products:

- IONPS-A-R1 Updated ION AC power supply module for the 19-slot ION chassis

### **New Features and Enhancements:**

The following is a list of new features and enhancements in version 1.2.6 of the IONPS-A-R1.

- Fixed a power-up sequencing issue that caused the incorrect reporting on Temperature and Fan Speed.

### **Known limitations:**

- The IONPS-A and the IONPS-A-R1 can be installed in either PS1 or PS2 power supply slots in the rear of the ION219-x chassis. However when the IONPS-A-R1 is in slot PS1 and the IONPS-A is in slot PS2, and both power supplies are operating in Primary mode, meaning they are in an unbalanced auctioneered load-sharing mode, the IONPS-A in slot PS2 will be providing the majority of the power required by the ION 19-slot chassis.

### **Related Documentation:**

- IONPS-A-R1 User Guide (33614)