



---

## SISPM1040-3248-L Release Notes

**Date:** Oct.29, 2018

**Version:** 8.40.428

---

### Overview

This release notes covers firmware version v8.40.428 for SISPM1040-3248-L.

### Release Changes and Enhancements

Firmware Version: v8.40.428

[Fixed]

- 
- \* Added upload Google map API key function.
  - \* No warm start event option in the event group.
  - \* Syslog shows "cold boot" when executing "reload warm" in CLI.
  - \* Can't link up with 10G when 10G port speed is auto mode.

### Known Limitations and Restrictions

Traffic is leaking from one private VLAN to other VLANs.