



SM8TAT2SA-DC Release Notes

Date: Jul.14, 2020

Version: 1.02.1476

Overview

This release notes covers firmware version v1.02.1476 and Mib file for SM8TAT2SA-DC.

Release Changes and Enhancements

[Added]

=====

- * Timeout expected behavior (save timeout settings)
- * "Keep IP Configuration" of "Restore Configuration to Factory Default" needs to keep IP Gateway.
- * syslog format is consistent with other switches.

[Bugs Fixed]

- *Web: During manual logout / login, the automatic logout timer behaves abnormally.
- *Reload defaults keep-ip affects reboot when the switch uses class B subnet mask.
- * PC's NIC has force 100Mfdx, while Restore Configuration to Factory Default, the port cannot link up.

Known Limitations and Restrictions

n/a