



EOCPxx4020-110 Release Notes

Date: September 6, 2016

Version: 0.4.0.1 and 0.4.0.2

Overview

This release note covers the requirements, important notes, and known limitations for the EOCPxx4020-110 PoE+ over Coax Ethernet Extender.

Access to configuration and monitoring of the EOCPxx4020-110 is available using a web browser.

Requirements:

Web browsers supported for the Web GUI include current versions of Internet Explorer, Mozilla Firefox, Google Chrome, Opera, and Safari.

Firmware version 0.4.0.1, version 0.4.0.2 and these release notes apply to the following products:

- EOCPD4020-110
- EOCPSE4020-110

Known Limitations:

- EOCP units are intended to be fully managed through a single IP address assigned to the Local unit. The following operations and settings cannot be performed on the Remote unit using the Web interface on the Local unit:
 - Hardware reset (can be done through Reset buttons or TN Ethernet Extender Tool)
 - Factory default reset (can be done through Reset buttons or TN Ethernet Extender Tool)
 - Security pairing and unpairing (can be done through Reset buttons or TN Ethernet Extender Tool)
 - Ethernet Link Settings, SFP Detection Setting and Primary Link can only be managed directly from the Local unit

Please consult user documentation for details on the best method to perform these operations and settings.

Related Documentation:

- EOCPxx4020-110 User Guide (33675)
- EOCPxx4020-110 Quick Start Guide (33689)
- TN Ethernet Extender Tool (33696)