



---

## ION C3110 Release Notes

**Date: February 24, 2020**

**Version: 2.0.3**

---

### Overview

This release note covers the requirements, important notes, new features and changes, addressed issues and known limitations for the ION C3110 product.

Management of the ION C3110 is available when it's installed in a managed ION Chassis by using a web browser or Command Line Interface (CLI) via the local USB port, telnet, or via SNMP.

### Requirements:

Firmware version 2.0.3 and these release notes apply to the following products:

- C3110-1013
- C3110-1014
- C3110-1039
- C3110-1040

### New Features and Enhancements:

The following is a list of new features and enhancements in version 2.0.3 of the C3110.

- Fixed an issue where trap messages, such as Link Up or Link Down on both the copper and the fiber ports, were not being generated.

### Related Documentation:

- ION C3100 Install Guide (33417)
- ION219-x Install Guide (33412)
- IONMM Install Guide (33420)

### MIBs:

- ION\_MIBs.zip file